

Fan Coil Builder v3.29a replaces v3.29

UPDATE DESCRIPTION

Fan Coil Builder v3.29a contains the following change:

- An error message was modified. This message appears when a 42B, Belted unit is selected and a motor is not available for the total static pressure specified. The original message content was "There is currently no hp available for the voltage – TSP combination that you have chosen. Please lower your TSP.". The new message also includes the recommendation to "Check the recommended operating range/limits." - in some situations reducing the total static pressure was not the solution to the problem.

INSTALLATION PROCEDURES

Installation via Internet Download

- Download the **ecat-fcb329a.exe** file from the Internet site and save it in a folder on your hard disk.
- Run Windows Explorer and double-click on the **ecat-fcb329a.exe** file. This launches the program installer.
- Follow the installation instructions that appear on your screen.
- Note: The current version of X Builder Framework and AutoDesk VoloView Express® should be installed prior to installing the Fan Coil Builder. Both can be downloaded from the internet site.

Running the Program:

- From the Windows desktop press Start, choose Programs and then choose Carrier E-CAT/E20-II programs.
- In the Carrier E-CAT/E20-II Programs group click on the Fan Coil Builder v3.29a item.

Minimum Computer Requirements:

- Hard Disk Space: 20 megabytes
- Random Access Memory: At least 64 megabytes
- Display Monitor: At least VGA with 600x800 resolution and 256 colors.
- Operating System: Windows 98, 2000, XP, Vista or Windows NT (with service pack 4 or later).
- The current version of XBuilder Framework should be installed prior to installing the Fan Coil Builder.

PREVIOUS VERSION INFORMATION

1. When Fan Coil Builder v3.29a is installed it will automatically replace Fan Coil Builder v3.29. There is no need to uninstall the v3.29 before installing v3.29a.
2. Data from Fan Coil Builder v3.29 is immediately usable in v3.29a. No data conversion is required.

SPECIAL NOTES

1. **XBuilder.** The latest version of XBuilder Framework should be installed before installing Fan Coil Builder.